

Fast Connect Stripping Tool

Function

The **Fast Connect Stripping Tool** is used for PROFIBUS / Ethernet cable stripping. The line end is prepared in one go ready for connection according to the Fast Connect standard.

Instructions of use

1. Adjust the knives at the side of the stripping tool using a hexagon key.
2. Place the PROFIBUS or Ethernet cable into the stripping tool.
Note: Leave the stripped line a bit longer. If need be, it can cut off later.
3. Hold the line tight and rotate the stripping tool around the line. Depending on the line type and the adjustment of the knives 2 to 4 rotations are necessary.
Note: Make sure that the line ends to be stripped for assembly are not wrenched.
4. If properly used, the PROFIBUS or Ethernet cable is almost ready for connection so that only the data line needs to be stripped still.
Infinitely variable steel blades provide for accurate stripping. Stripping of the cable sheath, braided screen and filler in one go.



Stripping Tools (PROFIBUS and Ethernet)



PROFIBUS Fast Connect Stripping Tool



Ethernet Fast Connect Stripping Tool

Ordering details	Art. No.
PROFIBUS Fast Connect Stripping Tool	110020032
Ethernet Fast Connect Stripping Tool	112020005